


PCT02016US

Fig.1



BEST AVAILABLE COPY

Fig.2




Fig.3




Fig.4




Fig.5




Fig.6




Fig.7




Fig.8A




Fig.8B




Fig.9




Fig.11




Fig.12




Fig.13A




Fig.13B




Fig.13C




Fig.14






Fig.15



第16図



Explanation of Reference Numbers

- 1 Base isolation device
- 2 Bridge support
- 3 Floor slab (structural element)
- 4 Elastic member
- 5 Damping member
- 6 Weight member
- 10 Base isolation device
- 11 Bridge support
- 12 Floor slab (structural member)
- 13 Support point
- 14 Tension member
- 14a Steel rod
- 14b Steel rod
- 14c Steel rod
- 15 First link piece
- 16 Second link piece
- 17 Energizing member
- 18 Damping member
- 19 Pin
- 20 Pin
- 21 Pin
- 22 Connection leg
- 23 Weights
- 24 Sensor
- 25 Controller
- 26 Frame member
- 27 Pin
- 28 Connection link piece
- 29 Connection rod
- 30 Connection plate

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.